Bid Notice Abstract

Request for Quotation (RFQ)

Reference Number 9120338

Procuring Entity DEPARTMENT OF TOURISM

Title Procurement of Service Provider for the Hyperbaric Chamber System Preventive Maintenance

Area of Delivery Metro Manila

Solicitation Number:	RFQ No. 2022 - 10 - 0176	Status	Pending
Trade Agreement:	Implementing Rules and Regulations		
Procurement Mode:	Negotiated Procurement - Small Value Procurement (Sec. 53.9)	Associated Components	2
Classification:	Goods	Bid Supplements	0
Category:	Services		
Approved Budget for the Contract:	PHP 429,000.00	Document Request List	0
Delivery Period:			
Client Agency:			
		Date Published	15/10/2022
Contact Person:	John Paulo Samonte Francisco		
	Administrative Assistant III 351 Sen. Gil Puyat Avenue Makati City Metro Manila	Last Updated / Time	14/10/2022 14:12 PM
		Closing Date / Time	18/10/2022 10:00 AM

Description

TECHNICAL SPECIFICATIONS

I. BIDDER: Service Provider

II. PROJECT TITLE: Hyperbaric Chamber System Preventive Maintenance

III. OBJECTIVES:

- A. To keep or retain the Hyperbaric Chamber System (HCS) equipment in a satisfactory operating condition through periodic inspections, calibration, and replacements; and
- B. To minimize the possibility of unanticipated production interruption or major breakdown by uncovering any condition which may lead to it.
- IV. MINIMUM REQUIREMENTS
- A. Must be registered with the Philippine Government Electronic Procurement System (PHILGEPS); and
- B. Must be willing to provide services on send-bill arrangement.
- V. SCOPE OF WORK

A service provider that will be in charge of the following:

DATE LOCATION BUDGET SOURCE OF FUND

October 2022 Lung Center of the Philippines, Diliman, Quezon City ₱ 429,000.00 2022 Work and Financial Program

PARTICULARS

ITEM QUANTITY

Purchase and installation of the following:

- Oxygen Analyzer 1 pair
- Bibs (oxygen delivery system) 4 pieces
- Power intercom speaker 1 pair
- Foam with upholstery 1 piece
- Stretcher 1 piece
- Timer 1 piece
- Air filter for the compressor 2 pieces
- Oil filter for the compressor 2 pieces
- Compressor Oil 4 liters
- Fire blanket 1 piece

Repair of the air banks including hydro test 2 tanks

Preventive maintenance of the compressor 1

Replacement of the following:

- Inner and outer lock rubber seal 2 pieces
- Fort wall window rubber 3 pieces
- Medical lock rubber seal lock 2 pieces
- Pressurized hose 6000 psi 15 meters
- Compression hoses 15 meters
- Oxygen regulator 1 piece

Repainting of the hyperbaric chamber

NOTE: Delivery of the requested items is at the Lung Center of the Philippines, Diliman, Quezon City

VI. CONTACT PERSON

Project Officer: Rachelle Anne R. Yoro

Office: Philippine Commission on Sports Scuba Diving

Address: The New DOT Bldg., Ground Floor, 351 Sen. Gil Puyat Avenue, Makati City, 1200 NCR Philippines

Contact Numbers: 0977-444-6505

Email Address: rachelle.yoro@divephilippines.com.ph

Line Items

Item No.	Product/Service Name	Description	Quantity	UOM	Budget (PHP)
1		Procurement of Service Provider for the Hyperbaric Chamber System Preventive Maintenance	1	Lot	429,000.00

Other Information

Eligibility Requirements

1. Mayor's/Business Permit issued by the city or municipality where the principal place of business of the prospective bidder is located, or the equivalent document for Exclusive Economic Zone Area,

In cases of recently expired Mayor's/Business permits, it shall be accepted together with the official receipt as proof that the bidder has applied for renewal within period prescribed by the local government unit.

- 2. PhilGEPS Registration Number
- 3. Latest Income/Business Tax Return (For ABC above PhP500, 000.00)
- 4. Original or Certified True Copy of Duly Notarized Omnibus Sworn Statement

Note: Kind submit your quotations together with your eligibility requirements thru email and sent it to jsfrancisco@tourism.gov.ph on or before 18 October 2022 at 10:00 am. Late and unsigned proposals shall not be accepted.

Created by John Paulo Samonte Francisco

Date Created 14/10/2022

The PhilGEPS team is not responsible for any typographical errors or misinformation presented in the system. PhilGEPS only displays information provided for by its clients, and any queries regarding the postings should be directed to the contact person/s of the concerned party.